

Date:

19.04.2025

Report Type:

Maintenance

Customer:

Name: Dr. Shilan	Location: Sul-
------------------	----------------

Machine:

Name: motus Ax 2	Type: Alexandrite
Model: M12A1	Serial No.: QM214102

Inspection:

Lamp shots: 1863566	Conductivity: 0.6 us
Rod shots: 19,213,753	Lenses: ok
Lamps No.: 8	Main shape: ok
Moveo use: 0%	Water leak: ok
Photod.: External 49 J Internal 49 J	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 0.3%	Power
Fiber test: ok	Before replacement: 30.6 = 540
Alarms: low energy	After replacement: 30.1 = 480

Report:


The Power of device was low

Actions:


I change flash lamp

Cost: \$2000 ^{DR} → \$1400

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square