

Date:

2025 / 4 / 22

Report Type:

Maintenance

Customer:

Name: Best Life Hos.	Location: scd
----------------------	---------------

Machine:

Name: H.R. <input type="checkbox"/>	Type: A lea
Model: Zenith	Serial No.:

Inspection:

Lamp shots: 760, 514	Conductivity: <
Rod shots: 2, 202, 160	Lenses: <
Lamps No.: ?	Main shape: <
Moveo use: -	Water leak: <input checked="" type="checkbox"/>
Photod.: External - Internal -	Electrical & Hydraulic parts: <
Results (phtod. & peltier)%: -	Power
Fiber test: <input checked="" type="checkbox"/>	Before replacement: -
Alarms: Coolant level	After replacement: -

Report:

Water Filter was damaged

Actions:

I change it

Cost:

± 450 dis ± 400

Engineer name & signature:

[Signature]

Customer Name & signature

[Signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square