

Date:

22-07-2025

Report Type:

Maintenance

**Customer:**

Name: Dr. Zana Abbas	Location: Sul
----------------------	---------------

**Machine:**

Name: Motor AX <input type="checkbox"/>	Type: Alexandrite
Model: M12A1	Serial No.:

**Inspection:**

Lamp shots: 2648, 174	Conductivity: 1.8 mS
Rod shots: 18, 938, 726	Lenses: not ok
Lamps No.: 4	Main shape: ok
Moveo use: 42 %	Water leak: ok
Photod.: External - Internal -	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: -	Power
Fiber test: ok	
Alarms: NO Alarm	After replacement: -

**Report:**


There was two lens (141 + 142) damaged

**Actions:**


1 change the lens

Cost: \$ 500  $\xrightarrow{\text{dis}}$  \$ 450

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448