



Date:

26-08-2028

Report Type:

Maintenance

Customer:

| | |
|------------------|---------------|
| Name: Dr. Shilam | Location: Sul |
|------------------|---------------|

Machine:

| | |
|--|-------------------|
| Name: Hair Removal <input checked="" type="checkbox"/> | Type: Alexandrite |
| Model: M112A1 | Serial No.: |

Inspection:

| | |
|------------------------------------|----------------------------------|
| Lamp shots: 1,409,435 | Conductivity: 0.7 us |
| Rod shots: 20,623,197 | Lenses: OK |
| Lamps No.: 6 | Main shape: OK |
| Moveo use: 0% | Water leak: OK |
| Photod.: External 518 Internal 498 | Electrical & Hydraulic parts: OK |
| Results (phtod. & peltier)%: 0.4% | Power |
| Fiber test: OK | |
| Alarms: low energy | After replacement: 30.6 = 470 |

Report:

- There was a problem in the Rod
- The Power was low

Actions:

- I fix the problem in the Rod
- I change flash lamp

Cost:

- Rod fix Free + Flash lamp → 81200

Engineer name & signature:

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Customer Name & signature

Main Office: Erbil, Mahmood Alhafeed Square