

Date:

15-03-2025

Report Type:

Maintenance

Customer:

Name: Dr. Sivan	Location: Sul
-----------------	---------------

Machine:

Name: motor Ax <input type="checkbox"/>	Type: Alex andrite
Model: M12 A1	Serial No.:

Inspection:

Lamp shots: 1,719,100	Conductivity: 12.8 us X
Rod shots: 16,220,480	Lenses: not ok (141)
Lamps No.: 8	Main shape: on
Moveo use: 0 %	Water leak: ok
Photod.: External 478 Internal 478	Electrical & Hydraulic parts: on
Results (phtod. & peltier)%: 1.2 %	Power
Fiber test: on	
Alarms: low energy	After replacement: 30.6=495

Report:

- Low energy two times + shimmer
- The refractor and rod filter must be change

Actions:

I change flush lamp

Cost:

82000 dis → 81500

Engineer name & signature:

Customer Name & signature

د. سیستان فاروق
ژ. تیماری سنیدیکا

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448