

report

No.: 015784

Date:

2025/6/29

Report Type:

etamaintace

Customer:

Name: <u>Basim Hos.</u>	Location: <u>sul</u>
-------------------------	----------------------

Name: <u>H.R</u>	<input type="checkbox"/>	Type: <u>Alex Indiyag</u>
Model: <u>Again</u>		Serial No.:

Inspection: <u>Alex Indiyag</u>	
Lamp shots: <u>1,659,992 / 41,330</u>	Conductivity: <u>-</u>
Rod shots: <u>2,227,992 / 42,323</u>	Lenses: <input checked="" type="checkbox"/>
Lamps No.: <u>4 / 1</u>	Main shape: <input checked="" type="checkbox"/>
Moveo use: <u>- / -</u>	Water leak: <input checked="" type="checkbox"/>
Photod.: External <u>-</u> Internal <u>-</u>	Electrical & Hydraulic parts: <input checked="" type="checkbox"/>
Results (phtod. & peltier)%: <u>93,1</u>	Power Before replacement: <u>-</u> After replacement: <u>-</u>
Fiber test: <input checked="" type="checkbox"/>	
Alarms: <u>Low water level</u>	

Report:

و بعد ترميمه عاودت العمل

Actions:

تغيير المصابيح

Cost: \$ 350 dim \$ 300

Engineer name & signature:

Customer Name & signature

[Handwritten signature]

[Handwritten signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448