

Report Type:

Date:

12-03-2025

Maintenance

Customer:

Name: Royal Hospital	Location: Sul
----------------------	---------------

Machine:

Name: Epicure <input checked="" type="checkbox"/>	Type: Alexandrite
Model: Zenith	Serial No.:

Inspection:

Lamp shots: 1,600,314	Conductivity: —	
Rod shots: 2,642,041	Lenses: ok	
Lamps No.: 1	Main shape: ok	
Moveo use: —	Water leak: not ok	
Photod.: External - Internal -	Electrical & Hydraulic parts: ok	
Results (phtod. & peltier)%: —	Power	
Fiber test: ok		Before replacement: —
		After replacement: —
Alarms: water level		

Report:

The ~~water~~ filter of water was damaged

Actions:

I change the filter

Cost:

8400

Engineer name & signature:



Customer Name & signature

