

Date:

2025/6/15

Report Type:

Maintenance / Check

Customer:

Name: <u>Badshih Hos.</u>	Location: <u>Halabja</u>
---------------------------	--------------------------

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓ / ✗
—	—	—	—	—	—
A.H.R	Alexa	Combi	IATA 220100090	839,812	✓
Zimmer	Air cooling	Conquest	AC80274264	—	✓
Hydra	section	pdT	1651911222	1,228,412	✓
H.Fu	Altrasound	Hipro-V	—	—	✓
RF	microwave	Ashley	Ash 2011018	—	✓
CO-switch	ndigag	2-10	ADPK 2002022	1,457,443	✓
CO2 laser	CO2	small	Tsmx 2706036	—	✓

Report:

1-Zimmer: The motor was damaged
 2-Combi: There is a spot on the lens

Actions:

1-Zimmer I change the motor
 2- the lens will change when need

Price:

\$ 500

Customer Name & signature

Engineer name & signature:

[Signature]

[Signature]
 2/10