

Date:

06-08-2025

Report Type:

Maintenance

**Customer:**

Name: center Pavilion	Location: Sul-
-----------------------	----------------

**Machine:**

Name: Hair Remover <input checked="" type="checkbox"/>	Type: Alexandrite
Model: motus AX	Serial No.:

**Inspection:**

Lamp shots: 2,148,721	Conductivity: 1.5 us
Rod shots: 1124613	Lenses: OK
Lamps No.: 6	Main shape: OK
Moveo use: 0 %	Water leak: OK
Photod.: External 46J Internal 46J	Electrical & Hydraulic parts: OK
Results (phtod. & peltier%): 30%	Power
Fiber test: OK	
Alarms: low energy	After replacement: 39.6 = 490 J

**Report:**

low energy


**Actions:**

I change flush lamp


**Cost:**

\$2000 → \$1400

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square